



323/324/325 Clamp Meters Quick Reference Guide

⚠ Warning


To prevent possible electrical shock, fire, or personal injury, read the "323/324/325 Safety Sheet" before you use this Product.



325




324




323


OFF




323




324/325



☀




OFF




A


~A 323, 324
A 325




~V ~V Ω




Ω




323 <70Ω
324/325 <30Ω



HOLD




20 V




>30 V



324, 325




Hz 325



AC/DC & ZERO



324, 325



+

